

**PUR-1710**  
**SWIMMING POOL ESURFACING AND ASSOCIATED IMPROVEMENTS**

Item No.	Item Description					
1	<b>Swimming Pool Repairs and Resurfacing—all necessary mobilization, site preparation, labor, materials, equipment, and related services necessary to complete the work.</b>					
	Supplier	QTY	UOM	Unit Price	Total Price	Supplier Notes
	The Pool People, Inc. Sykesville, MD	1	Lump Sum	\$118,750.00	\$118,750.00	
	USA Construction LLC Cumming, GA	1	Lump Sum	\$1,994,729.00	\$1,994,729.00	
	Winkler Pool Management, Inc. Hyattsville, MD	1	Lump Sum	\$92,335.88	\$92,335.88	Within 45 Days of Acceptance, Weather Permitting

Item No.	Item Description					
2	<b>CONTINGENT-Removal and Repair of Unbonded Plaster in Excess of 100 Square Foot Included in Lump Sum Price</b>					
	Supplier	QTY	UOM	Unit Price	Total Price	Supplier Notes
	The Pool People, Inc. Sykesville, MD	1	EA	\$5.40	\$5.40	S.F. is per layer/coat of delaminated plaster. Example: 1 layer= \$5.40 per s.f.; 2 layer=\$10.80 per s.f; etc.Areas with 2 or more layers/coats of plaster delaminated will require parging to build up the surface. Parging is per sqft at the rate of \$5.40 per s.f.
	USA Construction LLC Cumming, GA	1	EA	\$352,011.00	\$352,011.00	
	Winkler Pool Management, Inc. Hyattsville, MD	1	EA	\$14.40	\$14.40	